In the Specification:

Please amend the paragraph that begins on page 13 and extends to page 14 as follows:

In an alternative embodiment, an intermediate buffer vessel is used to store the supercritical cleaning solution before delivery to the process vessel. Figure 3 shows a solvent delivery mechanism, 104B (within dotted line area), which uses such a buffer vessel. Solvent delivery mechanism 104B includes many of the components that were described for solvent delivery mechanism 104A in Figure 2. In this case, supercritical cleaning solution leaving heat exchanger 118 enters a buffer vessel 126. Buffer vessel 126 has a volume to hold sufficient supercritical cleaning solution to rapidly fill process vessel 106 for processing. In a preferred embodiment, buffer vessel 126 holds a volume of supercritical solution to equal between about 5 and 25 times the volume of the process cavity (which holds the wafer or wafers) in process vessel 106. If a recirculation system is included with the wafer cleaning system, then buffer vessel 126 holds a volume of supercritical solution equal to between about 5 and 25 times the combined volume of the process cavity and the volume of the recirculation system. In this way, processing is expedited because the system can be charged with supercritical solution much faster.

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:	
	□ BLACK BORDERS
	☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
	☐ FADED TEXT OR DRAWING
	☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
	☐ SKEWED/SLANTED IMAGES
	☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
	☐ GRAY SCALE DOCUMENTS
	☐ LINES OR MARKS ON ORIGINAL DOCUMENT
	☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.